

79 63

1966 AUG 2 20 15Z

25X1

25X1

ATTN:

25X1

1. A ROLL OF 35MM NON-SPROCKETED TRACKER FILM WAS RECEIVED ON A FLANGELESS PLASTIC CORE FOR EVALUATION.

3 AUG 1966

B. APPROXIMATELY 0.3 INCH OF THE TERRAIN IMAGE ALONG THE CLOCK FILM EDGE IS FAINT AND DEGRADED. THIS IS POSSIBLY DUE TO AN OBSTRUCTION INSIDE THE CAMERA SLIT.

C. SEVERAL FINE LONGITUDINAL MINUS DENSITY STREAKS
ARE PRESENT THROUGHOUT THE MISSION.

D. BANDING IS PRESENT THROUGHOUT. IT IS MINOR IN MOST INSTANCES BUT AT TIMES BECOMES QUITE SEVERE.

E. A SMALL GROUP OF SCRATCHES ARE LOCATED IN THE METERING AREA BETWEEN FRAMES ON BOTH FILM EDGES. THEY ARE OUTSIDE THE FORMAT AND APPEAR TO BE CAMERA INDUCED. NUMEROUS

DATE	DESCRIPTION	AMOUNT	BALANCE
1	1		
2	2		
3	3		
4	4		
5	5		
6	6		
7	7		
8	8		
9	9		
10	10		
11	11		
12	12		
13	13		
14	14		
15	15		
16	16		
17	17		
18	18		
19	19		
20	20		
21	21		
22	22		
23	23		
24	24		
25	25		
26	26		
27	27		
28	28		
29	29		
30	30		
31	31		
32	32		
33	33		
34	34		
35	35		
36	36		
37	37		
38	38		
39	39		
40	40		
41	41		
42	42		
43	43		
44	44		
45	45		
46	46		
47	47		
48	48		
49	49		
50	50		
51	51		
52	52		
53	53		
54	54		
55	55		
56	56		
57	57		
58	58		
59	59		
60	60		
61	61		
62	62		
63	63		
64	64		
65	65		
66	66		
67	67		
68	68		
69	69		
70	70		
71	71		
72	72		
73	73		
74	74		
75	75		
76	76		
77	77		
78	78		
79	79		
80	80		
81	81		
82	82		
83	83		
84	84		
85	85		
86	86		
87	87		
88	88		
89	89		
90	90		
91	91		
92	92		
93	93		
94	94		
95	95		
96	96		
97	97		
98	98		
99	99		
100	100		

- 2 -

SCRATCHES ARE LOCATED BETWEEN FRAMES 431, 482 AND 433.

F. THE CLOCK AND FRAME COUNTER ARE SMEARED AND DOUBLE
IMAGED ON FRAMES 483, 484, 485 AND 523, BUT THE TERRAIN
IMAGERY IS SHARP.

S E C R E T

R

-END OF MESSAGE-

1